

Non-Towered Airport Operations and Midair Collision Avoidance - May Topic of the Month

Event Details

Per the General Aviation Joint Steering Committee Midair collisions are a persistent and deadly threat to aviation safety. From 2016 to 2021, there were 43 reports of midair collisions involving GA operations in the United States, resulting in 79 fatalities for an average of 8.6 per year.

Teaching Points:

- Highlights from the recently released Advisory Circular AC 90-66C Non-Towered Airport Flight Operations.
- Introduction to Advisory Circular AC 90-48E Pilot's Role in Collision Avoidance.
- Review of a typical GA Midair Collision scenario.
- Visual scanning techniques to enhance operational safety.

Thu, May 23, 2024 at 18:30 EDT

--

--

--

Foreign, FN



Contact: Mark Auer

(614) 255-3004

mark.d.auer@faa.gov

Select #: GL07129773

FPM MARK AUER n/a

You are invited to a ZoomGov meeting.
When: May 23, 2024 06:30 PM Eastern Time (US and Canada)

Register in advance for this meeting:
https://faavideo.zoomgov.com/meeting/register/vJIsf-Gtrj4tGNjLA_AsRoY79XjlJGpqth4

**** NOTE** - If the shortcut above fails to redirect you to the Zoom registration site. Please copy and paste the link into your browser to complete the registration process.

After registering, you will receive a confirmation email containing information about joining the meeting.

A message from the National FAASTeam Manager

Earn your WINGS to get a chance to win a prize. Go to <https://www.wingsindustry.com/WINGS-Sweepstakes> for more info. Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

Sign up for the FAA's safety services at www.faasafety.gov!

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the “Contact Information” area of the meeting/event notice. Note that two weeks is usually required to arrange services.