

# Garmin AT Repair Station Manual SOP-053 Recurrent Training.

Slideshow Review of Garmin AT Repair Station Manual Rev E. This will include Garmin SOP-0053 Sec. 5.2.1 Rosters, Sec. 5.2.2 Operation, Sec. 5.2.5 Tools and Equipment, Sec. 5.2.6 Capabilities List, Sec. 5.2.7 Repair Station Training Program, and Sec 5.3 Quality Control Manual.

**Directions:** Corsair Conference Room.

## A message from the National FAASTeam Manager

Invite a fellow pilot to the next WINGS Safety Seminar in your area.

Sign up for the FAA's safety services at [www.FAASafety.gov](http://www.FAASafety.gov)!

## Event Details

**Tue, Feb 10, 2015 - 09:00 PST**

**Garmin AT**

2345 Turner Road SE

Salem, OR 97302



**Contact: DEAN ALLEN BOEDIGHEIMER**

**(503) 391-3236**

[dean.boedigheimer@garmin.com](mailto:dean.boedigheimer@garmin.com)

Select #: NM0958734

Representative DEAN ALLEN

BOEDIGHEIMER

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.