FAASTeam presents:

## February Topic of the Month - Mountain Flying

Prepared by the Colorado Pilots Association, this seminar will explore valuable information compiled by veteran mountain pilots. Although it is not a comprehensive mountain flying course, this seminar's cursory review of mountain weather, reading the clouds, and planning a mountain cross country will enhance the safety of your flight in the Great Smoky Mountains or the Rocky Mountains.

**Directions:** From I - 77, take Exit 82C to Route 161 [Celanese Road] westbound towards York, SC. The airport is approximately 6 miles West of I-77, on the right, abutting and visible from Celanese Turn right at the stoplight onto Museum Road, past the National Guard Armory, bearing right onto Airport Road, past the Fire Station and FlyCarolina, to the brick terminal building on the right, with parking rom available. From I-85, take Exit 102 unto Highway 5 towards York where Hwy 5 joins Hwy 161. Turn left onto Hwy 161 eastbound, approximately 15 miles toward Rock Hill. Hwy 161 joins Cleanese eastbound and about 2 miles to museum Road, turn left at the stoplight onto Museum Road as then as explained above.

## A message from the National FAASTeam Manager

Invite a fellow pilot to the next WINGS Safety Seminar in your area.

Join us on Facebook: https://www.facebook.com/groups/GASafety/ Sign up for the FAA's safety services at www.FAASafety.gov!

## **Event Details**

Thu, Feb 21, 2019 - 19:00 EST Rock Hill York County Bryant Field

550 Airport Road

**Terminal Building Conference** 

Room

Rock Hill, SC 29732



Contact: WILLIAM WALTER GRANNIS (803) 230-1373 lostcomm7600@comporium.net

Select #: SO1388653

Representative WILLIAM WALTER GRANNIS

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.