

KSFB IMC Club Presents Personal Minimums and Weather Cams

- General aviation accidents have resulted from loss of control and controlled flight into terrain while flying in areas where weather information is largely unavailable.
- Near real time weather information, especially in mountainous areas is not commonly available but camera views of those locations can greatly aid pilots in determining whether there are sufficient ceiling and visibility to support safe flight.
- Pilots should be made aware of the presence of weather cameras and they should be instructed in their use.
- In consultation with a flight instructor, Pilots should develop a set of personal weather minimums and periodically review and revise that reflect to reflect personal capabilities.

Event Details

Mon, Aug 21, 2023 at 19:00 EDT
Vigilante Room, Sanford Airport
(KSFB)

1200 Red Cleveland Blvd., Sanford,
FL

Sanford, FL



Contact: Brent P. Moran

8134660021

brentmar@earthlink.net

Select #: SO15123470

Representative BRENT MORAN n/a

The Vigilante Room at Sanford Airport; it's in the Rental Car Building near the Commercial Airline Terminal. If you fly in to KSFB for this WINGS event, you can park at Million Air FBO and get a courtesy ride over to the seminar's location in the Vigilante Room. If you drive, you can park in short term parking and parking validation is available at the conclusion of the meeting.

A message from the National FAASafety Team Manager

Earn your WINGS to get a chance to win a prize. Go to <https://www.wingsindustry.com/WINGS-Sweepstakes> for more info. Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

**Join us on Facebook: <https://www.facebook.com/groups/GASafety/>
Sign up for the FAA's safety services at www.faasafety.gov!**

The FAA Safety Team (FAASafety Team) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.