

Aircraft Component Safety Wiring

- Pilots and mechanics should note component safety provisions during inspections.
- Safety wire and devices must be properly installed in order to be effective.
- Safety wire should be installed so that tension is applied in the component tightening direction.
- Castellated nuts should have cotter keys installed.
- At least 1/32 inch of bolts should protrude from fiber lock nuts.

From I-95 exit 220 turn east on Garden Street (406) approximately three miles, turn left on North Williams Ave. approximately 1 mile on the left. Building 10, in the class room.

A message from the National FAASTeam Manager

Earn your WINGS to get a chance to win a prize. Go to <https://www.wingsindustry.com/WINGS-Sweepstakes> for more info. Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

Event Details

Sat, Sep 6, 2025 at 09:30 EDT

Arthur Dunn Airpark

480 North Williams Ave

Classroom in Bldg. 10

Titusville, FL



Contact: Joseph Schmalz

7542133952

skwy99@gmail.com

Select #: SO15138946

Lead Representative Joseph Schmalz n/a

**Join us on Facebook: <https://www.facebook.com/groups/GASafety/>
Sign up for the FAA's safety services at www.faa.gov!**

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the “Contact Information” area of the meeting/event notice. Note that two weeks is usually required to arrange services.