

FAASTeam presents:

**EVENT POSTPONED Due to Location Unavailability The PHPA  
and HAI Safety Seminar**

Lunch is available for a small donation and will begin at 12:00 Noon. Contact Tony Byrnes - (see contact info below)

TC Corell will discuss how to develop an effective flight training program, tailored to your mission.

The methods he used in creating the current training and safety program at Southern California Edison's Aviation Operations, are simple and effective, and can be tailored to any needs.

TC Corell is the Chief Pilot at Southern California Edison - Aviation Operations

**Directions:** EVENT POSTPONED Due to Location Unavailability!

Driving Directions: Take Euclid Ave. to Merrill Ave. - Turn East on Merrill Ave. to Cal Aero Dr. - Turn South onto Cal Aero Dr. - Parking available on the eastside of Cal Aero Dr., next to the hangars. \*\*Locate the PHPA Event sign and enter the gate there.

Fly-in Directions: Transient parking at the base of the tower. - Fuel and parking available at Flying Tigers Aviation, Ph: 909-606-3300 - (Located on the eastside of the tower) - Walk north from parking between the hangar rows to Row 170 - Walk west to Hangar 9 on the south-side of the hangar row.

**A message from the National FAASafety Team Manager**

Invite a fellow pilot to the next WINGS Safety Seminar in your area.

Sign up for the FAA's safety services at [www.FAASafety.gov](http://www.FAASafety.gov)!

**Event Details**

**Sat, Jan 28, 2017 - 10:00 PST**

**Hangar 9, Row 170**

7000 Merrill Ave.

Chino, CA 91710



**Contact: Anthony Byrnes**  
**(714) 345-5062**

[arbyrnes42@hotmail.com](mailto:arbyrnes42@hotmail.com)

Select #: WP2173416  
FPM KARLA JEAN BORDEN

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.