



FEDERAL AVIATION ADMINISTRATION



FLIGHT ADVISORY
GPS Testing
ACC GPS 11-03
April 8, 2011 – April 9, 2011
Pueblo, CO

GPS testing is scheduled as follows, which may result in unreliable or unavailable GPS signal.

A. Location: Centered at 373001N/1035621W or the TBE VOR 311.98 degree radial at 21.72NM.

B. Dates and times:

08 APR 11	1900Z - 2200Z
09 APR 11	1900Z – 2200Z

C. Duration: Tests will be conducted in 3 hour blocks.

D. During testing, the GPS signal may be unreliable or unavailable within a 340NMR centered at 373001N/1035621W or the TBE VOR 311.98 degree radial at 21.72NM at FL400, decreasing in area with decrease in altitude to 290NMR at FL250, 180NMR at 10,000 FT MSL, and 200NMR at 4,000 FT AGL.

E. Pilots are strongly encouraged to report anomalies during testing to the appropriate ARTCC to assist in the determination of the extent of GPS degradation during tests.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.

