



FEDERAL AVIATION ADMINISTRATION



**FLIGHT ADVISORY**  
**GPS Testing**  
**CHLK GPS 11-11**  
**September 24, 2011 – September 28, 2011**  
**China Lake, CA**

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

- A. Location: Centered at 360054N/1173137W or the BTY VOR 218.9 degree radial at 63.3NM.
- B. Dates and times: 24-28 Sep, 2011 0700-1300Z
- C. Duration: Each event may be intermittent during the test periods.
- D. During testing, the GPS signal may be unreliable or unavailable within a 295NMR centered at 360054N/1173137W or the BTY VOR 218.9 degree radial at 63.3 NM at FL400 and above, decreasing in area with decrease in altitude to 250NMR at FL250, 165NMR at 10,000 FT MSL, 135NMR at 4,000 FT AGL and 105NMR at 50 FT AGL.
- E. Pilots are strongly encouraged to report anomalies during testing to the appropriate ARTCC to assist in the determination of the extent of GPS degradation during tests.

**The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.**

**CHLK 11-11  
GPS INTERFERENCE TESTING**

