



FEDERAL AVIATION ADMINISTRATION




FLIGHT ADVISORY
GPS Testing
Cape Canaveral GPS 13-01
01 - 31 Aug, 2013
Cape Canaveral, FL

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

- A. Location: Centered at 282814N/0803448W or the MELBORNE, FL VOR (MLB) 008 degree radial at 22NM.
- B. Dates and times:

1 - 31 AUG 13 0000Z – 2359Z
- C. Duration: Each event may last the entire requested period.
- D. During testing, the GPS signal may be unreliable or unavailable within a 5NM radius centered at 282814N/0803448W or the MLB VOR 008 degree radial at 22NM from surface to FL400.
- E. Pilots are strongly encouraged to report anomalies during testing to the appropriate ARTCC to assist in the determination of the extent of GPS degradation during tests.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.



**Cape Canaveral 13-01
GPS INTERFERENCE TESTING**