

DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION

HONOLULU CONTROL FACILITY
760 WORCHESTER AVENUE
HONOLULU, HAWAII 96818

ISSUED: November 19, 2012

EFFECTIVE: November 26, 2012

HONOLULU CONTROL FACILITY LETTER TO AIRMEN NO. 12-03

SUBJECT: Honolulu Tower Areas of Non-visibility

CANCELLATION: November 26, 2014

Due to obstructed vision, Honolulu Tower is unable to provide air traffic services in the following areas.

1. On Taxiway RB when ASDE-X MLAT is out of service - from Taxiway M southbound to 200 feet past the golf course shoreline due to trees.
2. On sea Lane 4/22 - the approach end of sea lane 4/departure end of sea Lane 22 due to the Continental maintenance hangar.

Aircrews and ground crews are reminded that the movement of aircraft and vehicles in non-movement areas are the responsibility of the pilot, the aircraft operator, or airport management.



Linda S. Pellegrini
Air Traffic Manager
Honolulu Control Facility