

DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION

HONOLULU CONTROL FACILITY
760 WORCHESTER AVENUE
HONOLULU, HAWAII 96818

ISSUED: November 27, 2012

EFFECTIVE: December 3, 2012

HONOLULU CONTROL FACILITY LETTER TO AIRMEN NO. 12-11

SUBJECT: Parachute Operations at Dillingham Airfield


CANCELLATION: November 26, 2014

This Letter to Airmen supersedes HCF Letter to Airmen 12-09, same subject, which was effective on 11/26/2012.

Parachute operators conducting jumps in the Dillingham parachute jumping area are advised of the following procedures to comply with Federal Aviation Regulation (FAR) Part 105, Parachute Operations.

- a. Notify the Honolulu Control Facility (HCF) via fax (808) 840-6210 of parachute operations to be conducted. Information must be received no earlier than 24 hour before or no later than 1 hour before the parachute operation begins. Please include (FAR 105.15):
 - i. Date and time of the operation.
 - ii. Altitude at which the aircraft will be operated when parachutists exit the aircraft.
 - iii. Duration of the intended operation.
 - iv. Name, address, and telephone number of the person requesting the authorization.
 - v. Registration number of the aircraft to be used.
- b. When airborne, Air Traffic Control will expect three transmissions from the pilot.
 - i. Five minutes to jump.
 - ii. Jumpers away.
 - iii. All Jumpers down.

For more information, refer to the *Aeronautical Information Manual* under "Parachute Jumping Operations," or call the Honolulu Control Facility at (808) 840-6201.



Linda S. Pellegrini
Air Traffic Manager
Honolulu Control Facility