



FEDERAL AVIATION ADMINISTRATION



FLIGHT ADVISORY
GPS Interference Testing
CHLK GPS 15-15
03 - 18 November 2015
China Lake, California

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

A. Location: Centered at 360822N 1173846W or the BTY VOR 214 degree radial at 059 NM.

B. Dates and times: 03 – 04 NOV 15 1730Z – 2230Z
17 – 18 NOV 15 1730Z – 2230Z

C. Duration: Each event may last the entire requested period.

D. NOTAM INFO: NAV (CHLK GPS 15-15) GPS (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVAILABLE WITHIN A 476NM RADIUS CENTERED AT 360822N1173846W (BTY 214059) FL400-UNL DECREASING IN AREA WITH A DECREASE IN ALTITUDE DEFINED AS:

432NM RADIUS AT FL250,
375NM RADIUS AT 10000FT,
340NM RADIUS AT 4000FT AGL,
253NM RADIUS AT 50FT AGL.

E. Pilots are encouraged to report anomalies only when ATC assistance is required.

The time periods discussed in this advisory may be reduced or cancelled with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.

