



FEDERAL AVIATION ADMINISTRATION




**FLIGHT ADVISORY
GPS INTERFERENCE TESTING
FCAR 16-02
21-25 March 2016
Fort Carson, CO**

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal:

- A. Location: Centered at 383140N 1045437W or the PUB VOR 293 degree radial at 27NM.
- B. Dates and times: 21-25 MAR 2016 1730Z – 2330Z
- C. Duration: Each event may last the entire requested period.
- D. NOTAM INFO: NAV (FCAR GPS 16-02) GPS (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVAILABLE WITHIN A 41NM RADIUS CENTERED AT 383140N1045437W (PUB 293027) FL400-UNL DECREASING IN AREA WITH A DECREASE IN ALTITUDE DEFINED AS:

41NM RADIUS AT FL250,
41NM RADIUS AT 10000FT,
41NM RADIUS AT 4000FT AGL,
38NM RADIUS AT 50FT AGL
- E. Pilots are encouraged to report anomalies only when ATC assistance is required.

The time periods discussed in this advisory may be reduced or cancelled with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.



FCAR 16-02 GPS INTERFERENCE TESTING