



FEDERAL AVIATION ADMINISTRATION



**FLIGHT ADVISORY
GPS INTERFERENCE TESTING**

BLISS 17-03 (FORT BLISS)

**25-26 October, 2017
El Paso, Texas**

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

A. Location: Centered at 321608N1060603W or the ELP VOR 011 degree radial at 29NM.

B. Dates and times:

25 - 26 Oct 17 1300Z - 1400Z and 1900Z - 2030Z

C. Duration: Each event may last the entire requested period

D. NOTAM INFO: NAV GPS (BLISS GPS 17-03) (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI A 158NM RADIUS CENTERED AT 321608N1060603W (ELP 011029) FL400-UNL,
153NM RADIUS AT FL250
126NM RADIUS AT 10000FT
123NM RADIUS AT 4000FT AGL
90NM RADIUS AT 50FT AGL

E. Pilots are encouraged to report anomalies only when ATC assistance is required.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.

