

FEDERAL AVIATION ADMINISTRATION



FLIGHT ADVISORY GPS INTERFERENCE TESTING

BLISS 18-04 (FORT BLISS)

26 – 27 April 2018 Fort Bliss, TX

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

- A. Location: Centered at 315434N1060913W or the ELP VORTAC 041-degree radial at 09NM.
- B. Dates and times: 26 27 APR 18 = 1830Z 2100Z
- C. Duration: Each event may last the entire requested period.
- D. NOTAM INFO: NAV GPS (BLISS GPS 18-04) (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI A 15NM RADIUS CENTERED AT 315434N1060913W (ELP041009) FL400-UNL, 16NM RADIUS AT FL250 16NM RADIUS AT 10000FT 16NM RADIUS AT 4000FT AGL 26NM RADIUS AT 50FT AGL.
- E. Pilots are encouraged to report anomalies only when ATC assistance is required.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.

