



FEDERAL AVIATION ADMINISTRATION



**FLIGHT ADVISORY
GPS INTERFERENCE TESTING**

FORT SILL OKLAHOMA (FSOK) 18-55


**24 October – 06 November 2018
Fort Sill, OK**

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

- A. Location: Centered at 344145N0983310W or the SPS VOR 358 degree radial at 43NM.
- B. Dates and times:

24 – 27 OCT 18	1400Z – 2300Z
29 OCT – 2 NOV 18	1400Z – 2300Z
3 NOV 18	1400Z – 1830Z
5 – 6 NOV 18	1400Z – 1800Z
- C. Duration: Each event may last the entire requested period.
- D. NOTAM INFO: NAV GPS (FSOK GPS 18-55) (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI A 274NM RADIUS CENTERED AT 344145N0983310W (SPS358043) FL400-UNL, 229NM RADIUS AT FL250, 161NM RADIUS AT 10000FT, 129NM RADIUS AT 4000FT AGL, 68NM RADIUS AT 50FT AGL.
- E. Pilots are encouraged to report anomalies in accordance with the Aeronautical Information Manual (AIM) paragraphs 1-1-13 and 5-3-3.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.



FSOK 18-55 GPS INTERFERENCE TESTING