



FEDERAL AVIATION ADMINISTRATION



**FLIGHT ADVISORY
GPS INTERFERENCE TESTING**

CHLK 18-07 (CHINA LAKE)

**30 September – 26 October 2018
China Lake, CA**

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

A. Location: Centered at 360744N1173403W or the BTY VOR 213 degree radial at 056 NM.

B. Dates and times:


30 SEP 18	1830Z – 2230Z
1 OCT 18	1830Z – 2359Z
23 OCT 18	1100Z – 1300Z
24 – 25 OCT 18	0930Z – 1300Z
26 OCT 18	0700Z – 1000Z

C. Duration: Each event may last the entire requested period.

D. NOTAM INFO: NAV GPS (CHLK GPS 18-07) (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI A 308NM RADIUS CENTERED AT 360744N1173403W (BTY213056) FL400-UNL, 241NM RADIUS AT FL250, 156NM RADIUS AT 10000FT, 162NM RADIUS AT 4000FT AGL, 122NM RADIUS AT 50FT AGL.E.

E. Pilots are encouraged to report anomalies in accordance with the Aeronautical Information Manual (AIM) paragraphs 1-1-13 and 5-3-3.

The time periods discussed in this advisory may be reduced or cancelled with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.



CHLK 18-07 GPS INTERFERENCE TESTING