



FEDERAL AVIATION ADMINISTRATION



**FLIGHT ADVISORY  
GPS INTERFERENCE TESTING**

**FORT IRWIN CALIFORNIA  
(FTIRCA) 21-56 REVISION 1**

**06 – 19 September  
Fort Irwin, CA**

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

A. Location: Centered at 352121N1163405W or the HEC VOR 336 degree radial at 34 NM.

B. Dates and times (**Dates and times are based on GMT (Z).**):


06 – 10 SEP 21	DLY	0600Z – 1259Z	
11 SEP 21		1630Z – 1959Z	
12 SEP 21		0600Z – 1259Z	1630Z – 1959Z
13 SEP 21		0600Z – 0859Z	1830Z – 2229Z
14 SEP 21		0800Z – 1059Z	1830Z – 2229Z
15 SEP 21		0800Z – 1059Z	
16 – 17 SEP 21	DLY	1000Z – 1259Z	
18 SEP 21		0600Z – 0859Z	1630Z – 2229Z
19 SEP 21		0600Z – 0859Z	

C. Duration: Each event may last the entire requested period.

D. NOTAM INFO: NAV GPS (FTIRCA GPS 21-56) (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI A 271NM RADIUS CENTERED AT 352121N1163405W (HEC336034) FL400-UNL, 221NM RADIUS AT FL250, 148NM RADIUS AT 10000FT, 121NM RADIUS AT 4000FT AGL, 89NM RADIUS AT 50FT AGL.

E. Pilots are encouraged to report anomalies in accordance with the Aeronautical Information Manual (AIM) paragraphs 1-1-13 and 5-3-3.

**The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.**



## FTIRCA GPS 21-56 REVISION 1 GPS INTERFERENCE TESTING