



FEDERAL AVIATION ADMINISTRATION



**FLIGHT ADVISORY
GPS INTERFERENCE TESTING**

**FORT HUACHUCA ARIZONA
(FTHUAZ) 24-01**

**18 – 27 March
Fort Huachuca, AZ**

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

A. Centered at 313731N1101533W or the OLS VOR 055 degree radial at 33 NM.

B. Dates and times (**Dates and times are based on GMT (Z).**):


18 MAR 24		0300Z – 0559Z	1830Z – 2230Z
19 – 21 MAR 24	DLY	0300Z – 0559Z	
22 – 24 MAR 24	DLY	0300Z – 0559Z	1830Z – 2230Z
25 – 27 MAR 24	DLY	0300Z – 0559Z	

C. Duration: Each event may last the entire requested period.

D. NOTAM INFO: NAV GPS (FTHUAZ GPS 24-01) (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI A 215NM RADIUS CENTERED AT 313731N1101533W (OLS055033) FL400-UNL, 156NM RADIUS AT FL250, 87NM RADIUS AT 10000FT, 92NM RADIUS AT 4000FT AGL, 67NM RADIUS AT 50FT AGL.

E. Pilots are encouraged to report anomalies in accordance with the Aeronautical Information Manual (AIM) paragraphs 1-1-13 and 5-3-3.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.



FTHUAZ GPS 24-01
GPS INTERFERENCE TESTING

FTHUAZ GPS 24-01 GPS INTERFERENCE TESTING