



FEDERAL AVIATION ADMINISTRATION



**FLIGHT ADVISORY
GPS INTERFERENCE TESTING**

**FORT LIBERTY NORTH CAROLINA
(FTLBNC) 24-56 (REVISION 1)**

**28 September – 05 October
Fort Liberty, NC**

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

A. Centered at 350637N0791526W or the LIB VOR 160 degree radial at 46 NM.

B. Dates and times (**Dates and times are based on GMT (Z).**):


28 SEP – 05 OCT 24 DLY 1600Z – 2100Z

C. Duration: Each event may last the entire requested period.

D. NOTAM INFO: NAV GPS (FTLBNC GPS 24-56) (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI AN AREA DEFINED AS: 362748N0780524W TO 393630N0821201W TO 344516N0850947W TO 305429N0813922W TO 334844N0775746W TO 362748N0780524W, SFC-UNL.

E. Pilots are encouraged to report anomalies in accordance with the Aeronautical Information Manual (AIM) paragraphs 1-1-13 and 5-3-3.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.



FTLBNC GPS 24-56 (REVISION 1) GPS INTERFERENCE TESTING