

Cessna 208B, Cracked Bulkhead, ATA 5312

This submitter states, "The aft canted bulkhead (P/N 2612060-5) at station 474.40 has two cracks, each approximately 1.5 inches in length. During removal of this part, other damage was found. Both vertical stabilizer webs (P/N's 2631021-15 and 2631022-2) were replaced because of significant fretting, (*so too*) the aft bulkhead assembly (P/N 2612059-1)."



Cessna 208B, Cracked Bulkhead, ATA 5312



Total Part Time: 18,045.0 hours