
The APU *(auxiliary power unit)* goes off line as soon as it is loaded. The APU generator spline shaft *(was found)* sheared off."







Part Total Time: 1,492.0.0 Hours