

Ercoupe A1, Sheared Landing Gear Bolts, ATA 3211

A mechanic states, "These bolts are located at the top of the landing gear. Three of these bolts hold the spring gear on; all three failed.

The mechanic recommended these (NAS146-35) bolts in both main gears be replaced after each 1000 hours of time in service."

Part Total Time: 1,515.01 hours