

Orlando FSDO FAA Safety Team presents:

# Structural Corrosion

Why did a wing fall off a Cessna 210? What did Australian Civil Aviation Safety Authority do as a result? What did the Federal Aviation Administration do as a result? There are two general classifications of corrosion. Some cleaning solutions used in corrosion removal are, in themselves, potentially corrosive agents. In this FREE presentation, we will cover corrosion preventive maintenance to include the 13 specific actions. We will list 6 trouble spots for visual inspections. AMT Credit Available!

**Directions:** From Colonial Drive turn south on Rickenbacker Dr. Continue through the Fairgreen St intersection to the end of Rickenbacker Dr. and into the parking lot. Park in any available designated spot. Walk east to the Airport Administration Building.  
Orlando Executive Airport (ORL)  
365 Rickenbacker Dr.  
Orlando, FL 32802

### **A message from the National FAASafety Team Manager**

Earn your WINGS to get a chance to win a prize. Go to [www.wingsindustry.net](http://www.wingsindustry.net) for more info.

Join us on Facebook: <https://www.facebook.com/groups/GASafety/>  
Sign up for the FAA's safety services at [www.FAASafety.gov](http://www.FAASafety.gov)!

The FAA Safety Team (FAASafety Team) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.

## Event Details

**Thu, Feb 9, 2023 - 20:00 EST**  
**Orlando Executive Airport (ORL)**  
365 Rickenbacker Dr.  
Orlando, FL 32802



**Contact: Robert Breaux**  
**407-644-4298**

[FAASafetyTeam@CenturyLink.net](mailto:FAASafetyTeam@CenturyLink.net)

Select #: SO15118117

Lead Representative Robert Breaux